



PRIME ADVANTAGE

ULTRA HIGH SOLID CLEAR FINISH

You are about to apply the best looking and most durable finish on the market: Better than Oil, Water, Moisture Cure or any other technology!

PROFESSIONAL PROTECTION FOR HARDWOOD FLOORS™

FOR SCREEN & RECOATS



SPECIFICATIONS

- Solids 60+%
- Flash Point . . . >102°F
- Pot Life 2-4 hrs. @ Rm Temp
- Coverage 400 sf/g
- Sheen Gloss, Semi-Gloss, Satin, Matte
- Color Crystal Clear
- Available In . . 1g Containers
- VOC <275 g/L

LOW VOC
HIGH SOLIDS

FEATURES

- Long Open Time: 20-30 min. wet edge
- Ultra High Solids for Super Build
- Low VOC: Less than 275
- Easy to Apply: low viscosity, great flow & leveling
- Clear Formula: will never amber
- Scratch Resistance: Better than water, oil or uv products
- No Waiting: Full use after 24-36 hours after coat is dry.
- Years before refinish is necessary.

Toughest PoloPlaz Finish Ever Made

Prime Advantage is formulated to withstand even the most demanding floor conditions. With high solids and low viscosity, Prime Advantage is ideal for recoats and new installations or resands. Its crystal clear film will never amber.

When schedules run tight, choose Prime Advantage for a quick turnaround. Resume use of floor in just 24 hrs without the worry of scuffing or scratching. Prime Advantage is the toughest product in the industry so your floors continue to look great year after year. With a VOC limit below 275 g/L, Prime Advantage is the perfect choice for LEED projects.



TOLL FREE (800) 421-7319 | OFFICE (501) 985-1172 | FAX (501) 985-1359 | 1 Paradise Park Road, Jacksonville, AR 72076

MADE IN THE USA POLOPLAZ.COM

PROFESSIONAL PROTECTION FOR HARDWOOD FLOORS™

FOR SCREEN & RECOATS

PRODUCT APPLICATION



Temperature of materials should be 70-80° F.

Step 1: Once floor is properly abraded and free of contamination, tack with PK cleaner and allow to dry thoroughly (approx. 20-30 minutes) before coating with Prime Advantage. Final abrasion with 180 grit (i.e. 3M™ hook & loop discs with SPP Pad or equivalent) for Prime Advantage Finish (as it is a clear finish).

Wear Personal Protection.

Measure the Floor:

Proper coverage is 400 sq ft. per gallon. To Maintain proper rate of coverage: Light weight T-Bar application is preferred, but one can use a roller. Use a premium non shedding 3/16" or 1/4" inch nap cover. Roll finish out of a plastic tray to prevent puddles and gloss variance from puddles. Never use a metal pan!

Step 2: Remove lid from container (Part A) and mix thoroughly prior to catalyzing; Add Part B while stirring vigorously with a wooden stir stick. Never use a metal paint paddle. Product will not cure unless thoroughly mixed. Never use an out of date catalyst.

WARNING: *If catalyst (Part B) is not added and mixed thoroughly the material will remain wet and never cure!!! After catalyzing a container, identify with a ribbon of tape on the handle. It is easy to lose track of which are catalyzed.*

Step 3: Apply product. The wet edge of the product is about 20-30 minutes at 70° F. At 90° F, the wet edge is REDUCED. Cooler temps produce longer wet edge times. It is important to change applicators or rollers EVERY 45-60 MINUTES or as roller begins to breakdown. Clean up with Denatured Alcohol.

Step 4: After coating, turn on air conditioning or heat for air flow (open windows slightly if possible) to accelerate cure and to remove any odors present. At 70° F, the material will be cured 24 hours after the application is dry and ready for move in. Lower temps require longer cure.

Prime Advantage is Clear & Never Ambers!!

Use only PoloPlaz Hardwood Floor Cleaner. The more you maintain your floor, the longer it will last!
Thank you for using Prime Advantage!! Please send pictures to sales@poloplaz.com!!